

Product Data Reporting and Evaluation Program (PDREP)

Attachment Tool

User Guide 24 June 2016

Table of Contents

FOREWORD	1
INTRODUCTION	2
ATTACHMENT TOOL	3
SUMMARY	8
*Hold the "CTRL" key and click on paragraph to follow link.	

1 FOREWORD

This document is intended to guide the use of the various search tools provided for Product Quality Deficiency Reports (PQDR) in PDREP.

Refer to the appropriate PQDR instructions and manuals for information about DoD PQDR program requirements.

REFERENCES:

- a. DLAR 4155.24
- b. SECNAVINST 4855.3C
- c. SECNAVINST 4855.5A
- d. DoDD 5000.2
- e. NAVSO P3683B

2 INTRODUCTION

The PQDR Attachment Tool allows the designated Service or Agency user to attach all necessary documentation as needed for the PQDR.

The PDREP application is accessible via the Product Data Reporting and Evaluation Program home page: https://www.pdrep.csd.disa.mil/

First time PDREP users will need to submit a User Access request form, available on the NSLC home page. Click on <u>User Access Request Form</u> to download the form. Follow the directions on the form to submit the request for access to PDREP.

Requests for changes or improvement to any of the PDREP applications or NSLC Detachment Portsmouth home page should be submitted to:

Online in the PDREP Application

If you're already a PDREP User, log on to PDREP: https://www.pdrep.csd.disa.mil/

Click on the Feedback link at the top of the home page. The Customer Service Request (Feedback) form will open. Instructions for completion are located at the top of the form.

Customer Support Desk

Commercial Phone: (207) 438-1690 / DSN 684-1690

FAX: (207) 438-6535, DSN 684-6535

Mailing Address

Naval Sea Logistics Center Portsmouth Bldg. 153, 2nd Floor Portsmouth Naval Shipyard Portsmouth, NH 03804-5000

3 ATTACHMENT TOOL

The attachment tool is a part of several applications inside of PDREP. It does not function as a standalone application. Once you have clicked the *View/Upload files* for whatever module you are working in you will be presented the attachment screen (Figure 3.0).




Figure 3.0

a. Clicking the *Add New Attachment* button will take you to the Upload Attachment(s) screen (<u>Figure 3.1</u>). There are no file type restrictions for PDREP and the maximum individual file size is 25MB.

Note: Supply Discrepancy Reports (SDRs) that are required to flow through WebSDR (those records that have a non-DON action point) have additional restrictions. See Warnings listed on Upload Attachment(s) screen (<u>Figure 3.1</u>).

DO NOT UPLOAD ANY CLASSIFIED DATA TO PDREP




Figure 3.1

b. Click the *Browse*... button to open your computer's file manager. Your file manager may differ from what is shown in (Figure 3.2) depending on your operating system.




Figure 3.2

- c. Navigate to whatever file you are attempting to upload and select it. Click *Open*. Repeat as necessary to upload multiple attachments
- d. You may choose to add a Description and Comments to your attachment by clicking the *Edit* button (<u>Figure 3.3</u>) and the text boxes will show to add the information. Click *Save Edits* to add them to the attachments or *Cancel Edits* to discard them.
- e. If you have uploaded a file in error you may delete it from the record by clicking the *Remove* button (<u>Figure 3.3</u>).

OUO	Product Data Re	UNCLASSIFI eporting and Eval	ED uation Program (PDRE	FOUO EP)
DREP Home • Subm	it Feedback • Externa	al Links • PDREP Manua	uls User Profile:	• <u>loqout</u>
 Click Edit to update Fig. Click Remove to remote Click Upload All to said Click Cancel to undo one 	ile/Description, Comments ove file from upload list.			
Vord documents 'Read-C 1) Open document in MS 2) Choose 'Options' fron 3) Click the Save tab 4) Enter a 'Password to 5) Click OK	Only': S-Word n the Tools menu Modify'		s they are designated 'Read-Only	'. Procedure to make your MS-
rompted upon opening. VebSDR: WebSDR will o			GIF, JPG, JPEG, PDF, TXT,	
file Name: 1.PNG Description (Max 100	O chars):			
Comments (Max 500	chars):			
			^	
			~	
Save Edits Can	cel Edits			
File Name	Description	Comments	Edit Description /Comments	Remove File
1.PNG			Edit	Remove
			En	-
2.PNG			Edit	Remove
2.PNG 3.PNG			Edit	Remove
3.PNG	Cancel			
3.PNG Upload All		DRTSMOUTH, NH. Ven	Edit	

Figure 3.3

- f. Once you are satisfied with the files selected and added any desired descriptions or comments click the *Upload All* button. Your files will be added to the record and you will be returned to the Attachment module home page (Figure 3.4).
- g. You may still delete attachments or add a descriptions or comments as described above. In addition, the record will show the added date and the user code of the person who uploaded the attachment.

Note: Only the user who originally uploaded an attachment will see the "Delete" button on the attachment module page. Users may not modify any other user's attachments.




Figure 3.4

4 SUMMARY

This concludes the instructions for adding an attachment file to a PQDR record in PDREP. For instructions on other PDREP and PQDR processes please consult the other documents provided in this series. The PDREP Customer Support Desk is available to answer additional questions or to assist in data changes or exception processing and can be contacted as follows:

E-Mail: webptsmh@navy.mil

Commercial: (207) 438-1690

DSN: 684-1690

Fax: (207) 438-6535